









McGrath Airport


Pavement Condition Index (PCI) Measured Values for the Year 2003

PCI Values General Pavement Recommendations

	85 - 100	Preventative Maintenance
	70 - 84	Preventative / Corrective Maintenance
	60 - 69	Corrective Maintenance / Overlay
	55 - 59	Overlay / Rehabilitate
	40 - 54	Rehabilitate
	25 - 39	Reconstruct
	10 - 24	Reconstruct
	0 - 9	Reconstruct

[] Branch-Section Identifier









Airport Code: MCG
Site Number: 50487.*A



McGrath Airport


Pavement Condition Index (PCI)
Predicted Values for the Year 2004

PCI Values General Pavement Recommendations

	85 - 100	Preventative Maintenance
	70 - 84	Preventative / Corrective Maintenance
	60 - 69	Corrective Maintenance / Overlay
	55 - 59	Overlay / Rehabilitate
	40 - 54	Rehabilitate
	25 - 39	Reconstruct
	10 - 24	Reconstruct
	0 - 9	Reconstruct

[] Branch-Section Identifier









Airport Code: MCG
Site Number: 50487.*A



McGrath Airport


Pavement Condition Index (PCI)
Predicted Values for the Year 2005

PCI Values General Pavement Recommendations

	85 - 100	Preventative Maintenance
	70 - 84	Preventative / Corrective Maintenance
	60 - 69	Corrective Maintenance / Overlay
	55 - 59	Overlay / Rehabilitate
	40 - 54	Rehabilitate
	25 - 39	Reconstruct
	10 - 24	Reconstruct
	0 - 9	Reconstruct

[] Branch-Section Identifier

Airport Code: MCG
Site Number: 50487.*A



Runway 7-25
[6200]

[6200-03] PCI = 0

[6200-02] PCI = 3

[6200-01]

[6200-04]

25

Taxiway D/
North Turn Around
[400-01]

East Taxiway
[200]

[200-03] PCI = 0

[200-02] PCI = 0

[200-01]

North Ramp
[4100-01]

Retardent Ramp
[4200]

[4200-01]

[4200-02]

Taxiway I
[900-01]

Taxiway J
[1000-01]

Minimum PCI for Runway = 70
Minimum PCI for Taxiways and Aprons = 60

[] Branch-Section Identifier









Airport Code: MCG
Site Number: 50487.*A

Map Compiled July 2003
by Statewide Pavement Management, AK DOT&PF

McGrath Airport


Pavement Condition Index (PCI)
Predicted Values for the Year 2006

PCI Values General Pavement Recommendations

	85 - 100	Preventative Maintenance
	70 - 84	Preventative / Corrective Maintenance
	60 - 69	Corrective Maintenance / Overlay
	55 - 59	Overlay / Rehabilitate
	40 - 54	Rehabilitate
	25 - 39	Reconstruct
	10 - 24	Reconstruct
	0 - 9	Reconstruct

[] Branch-Section Identifier









Airport Code: MCG
Site Number: 50487.*A



McGrath Airport


Pavement Condition Index (PCI)
Predicted Values for the Year 2007

PCI Values General Pavement Recommendations

	85 - 100	Preventative Maintenance
	70 - 84	Preventative / Corrective Maintenance
	60 - 69	Corrective Maintenance / Overlay
	55 - 59	Overlay / Rehabilitate
	40 - 54	Rehabilitate
	25 - 39	Reconstruct
	10 - 24	Reconstruct
	0 - 9	Reconstruct

[] Branch-Section Identifier









Airport Code: MCG
Site Number: 50487.*A



McGrath Airport


Pavement Condition Index (PCI)
Predicted Values for the Year 2008

PCI Values General Pavement Recommendations

	85 - 100	Preventative Maintenance
	70 - 84	Preventative / Corrective Maintenance
	60 - 69	Corrective Maintenance / Overlay
	55 - 59	Overlay / Rehabilitate
	40 - 54	Rehabilitate
	25 - 39	Reconstruct
	10 - 24	Reconstruct
	0 - 9	Reconstruct

[] Branch-Section Identifier

Airport Code: MCG
Site Number: 50487.*A



East Taxiway
[200]

[200-03] PCI = 0
[200-02] PCI = 0
[200-01] PCI = 0

North Ramp
[4100-01]

Minimum PCI for Runway = 70
Minimum PCI for Taxiways and Aprons = 60

[] Branch-Section Identifier

Airport Code: MCG
Site Number: 50487.*A